Matthew Alkins
Date : 13.10.2026

Customer: Corey Besner
Vehicle: Landrover Defender Puma 90 2008



Repairs and modifications carried out since October 2023

- Aftermarket Seats and Sliding Rails installed
- Momo steering wheel installed
- Brake fluid flush (DOT4)

December 2023

- Starter Motor Replaced

January 2024

- Full Vehicle Service (100% Synthetic 5W-30 Rock Oil) + OEM Quality Filters
- Exhaust Pipe Repaired
- Gearbox Mounts Replaced
- New Tires Installed Maxxis Bravo A/T LT275/70R16 + Wheel Alignment

November 2024

- Ball Joints Anti Role Bar Replaced
- Clutch Master Cylinder Replaced
- Clutch Fluid Flush (DOT 4 Rock Oil)
- Engine Service (100% Synthetic 5W-30 Rock Oil)

- Differential Oil Replaced Front and Rear (100% Synthetic 80W 90 LSD)

May 2025

- Door Latch Tail Gate Replaced (Original key and barrel maintained) Central Locking

- Short Shifter (slickshift) Installed and adjusted.

- New Shifter Knob Installed

- New Battery Installed - Power King

Jan 2026

Extensive work done to Drivetrain, Suspension, Wheel Bearing, Swivel Hubs, Axel Seals

- Front axel and swivel hubs rebuild inclusive wheel bearings, seals, gaskets, swivels, king pins, ABS sensor seals and fittings, swivel hub grease.

- Rear Wheel Bearing, hub seals, gaskets and hardware replaced.

- Front Radius Arms rebuild with new bushings and hardware left and right side.

- Rear Trailing Arms rebuild new bushings and hardware left and right side.

- Rear Toplink Fulcrum and Ball Joint new bushings and hardware left and right side.

- Transfer Box Output shaft seals replacement front and rear.




MAHLE
1 Piece
Original equipment quality
OX 339/2 D


Synthesis
F
5W-30
5W-30
ROCK OIL
1L


DENSO
Made in China











